ECS Configuration Change Request

Page 1 of 4 Pages

CCR No. 97-0683A	**Logged Date** 5/9/97	**Rev.** A	**Request Type** CCR

Priority Routine ☐ Urgent ☒ Emergency ☐	**Affected Release** B	**Change Class** I I

Title (description)
FOS#B RBR Cleanup

Documents Affected	**Source Nos** (RID, NCR, Action Item, GSFC CCR, etc.) **or Tech Reference** AC-97-0048

RTM Change ☒   **Start New Baseline** ☐

Problem
FOS#B RBRs require cleanup to its text and RBR to L4 Links.

FOS-0040#B added a link in a previous CCR (97-0459A) that was approved but not implemented into the 4/18/97 baseline. Therefore, new requirement key was not reflected in the 4/18/97 RTM query tables.

Proposed Solution
Modify appropriate FOS#B requirement text. Break links between RBR FOS-0020#B to L4s C-MSS-56030 & C-MSS-56080 and break links between RBR FOS-0025#B to L4 C-MSS-56020 & C-MSS-56070. See attachments.

Change requirement key # and remove underline from "un-verified" attribute.

Impact Analysis:

Organizations Affected: BOO ☐   Contracts ☐   ECS Chief Eng ☒   FOS ☒   M&O ☒
Procurement ☐   QO ☒   Rel. Dev ☒   Rel. A ☐   Rel. C ☐   SCDO Arch. ☐
Science Off ☐   Security ☐   Subcontrct ☐   Sys. Eng ☒   Sys Verf Acpt ☒

Cost: None ☒   Small ☐   Medium ☐   Large ☐
(Not exceeding $100,000)   ($100,000 to $500,000)   (Over $500,000)

Schedule: None ☒   Other
Additional LOC none   Man-Months
Materials

Originator Carol Chachulski   (signed) Carol Chachulski   5/8/97
Signature   Date

Office FOS   Office Manager (signed) Andy Miller   5/8/97
Signature   Date

Disposition Approved ☒   Approved w/Comment ☐   Forward ☐   Disapproved ☐
Comments:

CCB Chairperson (signed) Paul Fingerman   5/9/97
Signature   Date

CM01OC96   *ECS*